

FITNESS CERTIFICATE

Reference to letter No. 3802 / 2019-20 dated 28.11.2019 of Chief Development Officer Rampur is being issued.

- | | | |
|---|--|------|
| 1. Name of the Officer | Er. Sunil Kumar, Er. Indra Singh, Junior Engineer | |
| 2. Name of the School | Green Wood Sr. Sec. School. | |
| 3. Location with name of Education District/Sub. District | Moulana Mohd. Ali Jauhar Road, Karim Bagh,
Rampur (UP). | |
| 4. Classification of Building as specified in column 4 of the application for fitness certificate and size Building No. 1 | Size | Year |
| | 1. L- 102ft, width 18ft, Height 38ft | 1982 |
| Building No. 2 | 2. L-58ft, width 28ft, Height 38ft | 1982 |
| | 3. L-50.6ft, width 17ft, Height 24ft | 1982 |
| 5. Period for which the certificate is issued | 4. L-115ft, width 26ft, Height 24ft | 1982 |
| | 1. L- 136ft, width 29ft, Height 24ft | 1997 |
| 8. Nature of defects , if any | Two Year | |
| a) Foundation and basement | No defect | |
| b) Superstructure | No defect | |
| c) Doors and Windows | No defect | |
| d) Wood work wrought and put up | No defect | |
| e) Roof | No defect | |
| f) Flooring | No defect | |
| g) Miscellaneous (Cracks, etc.) | No defect | |
| 9. Any major defects noticed which will render the building unsafe in any manner | No | |
| 8. Whether maintenance works have been done properly | Yes. | |
| 9. Whether the structure is sound or not for conducting classes | Sound. | |

CERTIFICATE

Letter No. 1223 / Inspection

Date:- 11/10/2020

Certified that the school building has been inspected on 23-09-2020 and found to be fit to conduct classes, for the period two year (w.e.f 23-09-2020) for the reasons stated above.

Place : Rampur.

Date : 23-09-2020.

(Hemant Kumar Singh)
Executive Engineer
C.D.P.W.D RAMPUR

22/9/2020

23/9/2020